



DRAWING NO. 1 General Assembly (Rev. 0)




DRAWING NO. 2 Unit, Mechanism (Rev. 0)


Apply grease (Foil G-311S) to
the places marked with ★.




DRAWING NO. 3 Unit, Frame U (Rev. 0)




DRAWING NO. 4 SA, Front Tension Arm (Rev. 0)




DRAWING NO. 5 Unit, Frame Rear (Rev. 0)




DRAWING NO. 6 SA, Frame Ribbon R (Rev. 0)




DRAWING NO. 7 SA, Base Guide Open (Rev. 0)




DRAWING NO. 8 Unit, Sensor Adjust (Rev. 0)




DRAWING NO. 9 Unit, Frame (Rev. 0)


DRAWING NO. 10 Unit, Top Cover (Rev. 0)




DRAWING NO. 11 SA, Ope-pane (Rev. 0)



DRAWING NO. 12 SA, Front Center (Rev. 0)



DRAWING NO. 13 SA, Front Right (Rev. 0)



DRAWING NO. 14 Unit, PCB (Rev. 0)

